

RENISHAW METROLOGY LIMITED

PRELIMINARY USER GUIDE

FANUC OTA

TOOL SETTING SOFTWARE

H/2000/6016

INDUCTIVE COMPATIBLE

This document covers:-
Kit A/4012/0475) Type 1
Tape A/4012/0476) Retrofit package
see appendix for details

This document covers:-
Inductive kit A/4012/0464

RENISHAW METROLOGY LTD

Copyright - Macro programs.

Copyright 1987 Renishaw Metrology Ltd.

Copyright - Documentation.

Copyright 1987 Renishaw Metrology Ltd.

The documentation and macro programs may not be reproduced, stored or transmitted, wholly or in part, in any form or by any means, without prior written permission of the copyright holder.

CONTENTS

	<u>Page no.</u>
Requirements	3
F15 Connection diagram	4
F15 Output Signal	6
Software/parameters	7
Notes on Fanuc OM Programs	11
Tool Offset Indicator #509	13
Operator and Programmer notes	14
:9020 Default macro	16
:9021 inch/metric program	17
:9014 Protected Positioning	18
:9011 X datum the tool probe	20
:9010 Z datum the tool probe	22
:9016 X tool setting	24
:9019 Z tool setting	26
Example - datum the tool probe on 4 faces of the cube.	28
APPENDIX Type 1 retrofit package	31 - 33

Requirements

1. This software is to be installed on the Fanuc OTA Control.

- 2.1 Information signals are required.
UIO only for the FI5 interface.

- 2.2 U014 and U015 when inspection software is to be installed with Renishaw Tool Setting Software. They are used for interface inhibit signals.

3. The software cycles described in this document are intended for the inductive (FI5).

4. Memory Capacity Utilised

Inductive System 7.5 metres approximately.

5. User macro A.




FIG 7





FIG 2

PROBE - DIAGNOSTIC RELATIONSHIP




FIG 5




FIG 6

RENISHAW METROLOGY LTD

Software


The Gauging Macro Programs form the software for the probe system. The programs are provided on Mylar Tape and must be registered within the main program memory store. The following instructions form the recommended installation procedure.

1. Examine the Program Directory and ensure that the following program numbers are available for use:


:9001
:9002
:9010
:9011
:9014
:9016
:9019
:9020
:9021

2. Set parameters for the loading of the macro programs.

Parameter 11



Parameter 10



The setting of the parameter will permit loading of the macro programs into the protected area of the memory.

3. Loading of the Tape.

The tape has been prepared to allow for a continuous load of all macro programs.

a) Load Tape to Tape Reader

b) Select EDIT Mode

c) Press

PRGM

 Button


d) Press

INPUT




 Button

When loading is finished remove the tape and store in a safe place.

5. The following parameters must be checked.



The setting of parameter will retain the tool offset vector when the RESET function is used in cycle. Failure to do so will result in the machine moving out of position either towards or away from the work, depending on the sign of the tool offset amount. Correctly set the probe will remain at the programmed depth.



Note

The explanations and methods of setting of the parameters is clearly laid out in the Fanuc Operators and Maintenance manuals. Please refer to those manuals in case of difficulty.

NOTES ON FAUC OT

1. The macro variable input is by integer value.
Trailing zeros must be used.

eg.

#126 = 4 (G65 H01 P#126 Q6)
is regarded as 0.006 mm
or 0.0006 inch

whereas

#126 = 4000 (G65 H01 P#126 Q6000)
is regarded as 6.000 mm
or 0.6000 inch

The Programmer must check all inputs.

2. The default must be entered before the probe is used.
:9020 enters default values to the axis target registers
and tool store numbers. Failure to do so will eliminate
the format checking of the first probe macro.
3. Inch-Metric

G65 P#100 Q -|20
 |21
 └

Must be stated before the first probe cycle. This value
is lost on power off, but will otherwise remain modal
provided it is not used for other purposes.

RENISHAW METROLOGY LTD

4. The variables used are as follows:-

* Reserved for inspection cycles.

Variable Name	Alphabet Position	Referred To
D	7	#107 *
R	18	#118 *
S	19	#119 *
X	24	#124
Z	26	#126
M	13	#113 *
T	20	#120
Inch/Metric	—	#100
H	11	#111 *
K	6	#106 *
P	16	#116 *

Input statements #124 or #126 are necessary everytime;

Input statements #100, #120 are compulsory.

- 4.1 Renishaw cycles will use common variables #100-#131. They can be used for other purposes if required with the exception of #100. If this is used it must be restated before the next Renishaw cycle. See common variable list.
- 4.2 Renishaw cycles use retained variables #505-#508 for the Tool setting package. #500-#510 should be reserved for inspection packages etc.
5. Renishaw cycles for the Tool setting package use program numbers :9001, :9002, :9010, :9011, :9014, :9016, :9019, :9020, :9021.:9000-:9030 should be reserved for other possible packages.

RENISHAW METROLOGY LIMITED

#509 Tool Offset Type Indicator.

This must be set when the software is installed according to the type of tool offset being used on the machine.

Setting of this variable will ensure that the correct tool offset variable numbers will be addressed by the software.

Set #509 = 0 or 1

Integer 0 will indicate Tool offset only.

1 will indicate Tool geometry and wear.

OPERATORS AND PROGRAMMERS NOTE

In gauging routines the CNC system will inhibit the override of feed rates. The Feed Hold button is still active.


Note:

1. If #100 is not set to 20 or 21 then a Format error will result. (591)
2. The macro to set #100 must be run at the beginning of any program containing a probe sequence.
3. The macro does not convert programs from inch to metric, and vice-versa. It converts a feed rate depending on the input data.

Correction Factors

Each face of the cube stylus has its own correction factor. The correction factor is the error between the nominal position of the face and its true position established by datuming.

Macro variable locations for the cube stylus correction factors



RENISHAW METROLOGY LTD

If the Inch code is input when metric values are required then the feed rates will be at inch units at metric speed.

e.g.

60mm/min

6mm/min

1mm/min

If the metric code is input when the inch values are required then the feed rates will be at metric units at inch speeds.

e.g.

1500in/min

150in/min

25in/min

In the last case damage may result to the probe at the high feed if the machine is unable to stop quickly. Also the accuracy will have been lost.

The programmer must enter the values required correctly.

RENISHAW METROLOGY LTD

:9020 DEFAULT MACRO

Function

This macro should be stated immediately before the first Renishaw cycle to set default values. If multi Renishaw cycles are called following each other, then it is not necessary to restate this macro, since it is called automatically at the end of each Renishaw cycle, to reset all input variables used with the exception of #100 which is left modal. The inch/metric variable (#100) should either not be used for other purposes, or it should be restated at the next probe cycle.

Example:

```
%  
: 0001  
  
. )  
. ) move to position etc.  
  
M98 P 9020                               Set defaults  
  
G65 P #100 Q21                             Inch/metric  
  
. )  
. )                               Other inputs  
  
M98 P ....                               Probe cycle call  
  
. )  
. )  
. )
```

This macro will set default values of 9999999 to all input variables, except #100.

RENISHAW METROLOGY LTD

:9021 INCH METRIC

(User Transparent Utility)

Format

G 65 H1 P #100 Q | 20 inch
 | 21 metric
 └

M98 P 9021 called inside Renishaw cycles.

General


This program is embedded within the probe cycle programs.
It's purpose is to calculate the required feed rate units used
within the cycles to inch or metric units depending on the
input variable #100, and to set a default value.

#128 = 1	gauging feed	} inch
#125 = 1 x 6 = 6	intermediate feed	
#123 = 1 x 60 = 60	rapid feed	
#117 = 1600	overtravel (Q) also default for #118 (R)	
#128 = 25	gauging feed	} metric
#125 = 25 x 6 = 150	intermediate feed	
#123 = 25 x 60 = 1500	rapid feed	
#117 = 4000	overtravel (Q) also default for #118 (R)	

Note:

The inch/metric variable (#100) should either not be used for
other purposes, or it should be restated at the next probe
cycle.

:9014 PROTECTED POSITIONING



Format

```

G65 H1 P#100 Q  $\left\{ \begin{array}{l} 21 \\ 20 \end{array} \right.$ 
G65 H1 P#124 Qx
G65 H1 P#126 Qz
G65 H1 P#1115 Q1
M98 P 9014
G65 H1 P#1115 Qo
    
```

Note*

This cycle can only be used prior to setting tools, if the inspection probe interface is inhibited. This may be achieved by programming G65 H1 P#1115 Q1 before and G65 H1 P#1115 Qo after the cycle is called. Alternatively suitable 'm' codes provided by the OEM may be used.

General

The Protected Positioning will move the probe to the target positions for the gauging cycle to take place. The probe should previously have been positioned to a safe place with the tool offset applied. The program will monitor the stylus for any type of trigger.

Should a trigger occur the macro will decide whether the trigger was a False Trigger, caused by vibration, or a collision.

Application

The probe is programmed to move to the start co-ordinates of a gauging cycle.

The resulting move is similar to using linear interpolation, except that no feed rate will be required, the actual value used will be taken from program :9021 (#123).

Inputs

G65 H1 P#100 Q	[21 20]	State 20 or 21 (G20/G21 inch/metric)
G65 H1 P#124 Qx		Target position in x
G65 H1 P#126 Qz		Target position in z

#100 compulsory

#124, #126, are optional

Note: #100 is modal - it should not be used for other purposes.

Errors

Errors occurring during the cycle will stop the machine and display an alarm number. See macro alarm list for guidance.


MACRO ALARM LIST

<u>ERROR</u>	<u>MESSAGE</u>	<u>REASON</u>	<u>ACTION</u>
586	Path Obstruction	The stylus hit an obstruction. The infra red beam was cut.	Edit the program or remove the obstruction.
587	False Trigger	Four false triggers were detected prior to this error message. The probe is out of position.	Check the probe stylus pressure. Check for vibration sources.

RENISHAW METROLOGY LIMITED

FUNCTION

TO DATUM THE TOOL PROBE WITH A CALIBRATED TURRET TOOL



INPUT DATA

Variable Name

Inch/metric

#100

Target Face Position

#124

OUTPUT DATA

X Axis Directional

#506 (X+)

Probe Compensation -

Cube Stylus

#508 (X-)

RENISHAW METROLOGY LIMITED

OPERATION

The calibrated tool is positioned with its geometry compensation active to a position above or in front of the cube stylus reference surface. The referencing move takes place from which the trigger point of the cube stylus is calculated in the X+, X- direction.

When subsequently used for datuming an unused tool the trigger point will provide the position of the tool edge in the unloaded condition of the machine.

eg. G65 H1 P#100 Q21
G65 H1 P#124 Q101560
M98 P9011

Data found from the use of this macro will be used in the datuming of any tool in the X+, X- direction.

ERROR

591 Format Error

A Value was not found in #124
(Default Occured).

592 Probe Open

The stylus is in contact with the workpiece before the reference move occurs.

The stylus is deflected by contamination in the probe eyelid (remove and clean) or by probe malfunction (check probe by diagnostics).

593 Probe Fail

The target face was not found within 4 mm of its expected position.


Check target value.

Check probe position prior to the macro cycle starts.

RENISHAW METROLOGY LIMITED

FUNCTION

TO DATUM THE TOOL PROBE WITH A CALIBRATED TURRET TOOL



MACRO :9010

INPUT DATA

Variable Name

Inch/metric

#100

Target Face Position

#126

Probe to Probe Indicator #118 (G65 H1 P#118 QI)

OUTPUT DATA

Z Axis Directional

#507 (Z+)

Probe Compensation -

Cube Stylus

#505 (Z-)

OPERATION

The calibrated tool is positioned with its offset (geom./wear) compensation active to a position behind or in front of the cube stylus reference surface. The referencing move takes place from which the trigger point of the cube stylus is calculated in the Z+, Z- direction.

When subsequently used for datuming an unused tool the trigger point will provide the position of the tool edge in the unloaded condition of the machine.

eg. G65 H1 P#100 Q21
G65 H1 P#126 Q50123
M98 P9011

Data found from the use of this macro will be used in the datuming of any tool in the Z+, Z- direction.

ERROR

591 Format Error

A value was not found in #126
(Default Occured)

592 Probe Open

The stylus is in contact with the workpiece before the reference move occurs.

The stylus is deflected by contamination in the probe eyelid (remove and clean) or by probe malfunction (check probe by diagnostics).

593 Probe Fail


The target face was not found within 4 mm of its expected position.

Check target value.

Check probe position prior to the macro cycle starts.

FUNCTION

TO SET A TOOL IN THE X DIRECTION. TO ZERO THE WEAR OFFSET
AND ESTABLISH A NEW GEOMETRY OFFSET.



MACRO :9016

INPUT DATA

Variable Name

Inch/metric

#100

Traget Face Position

#124

Tool No

#120

OUTPUT DATA

The tool wear store is zeroed and the geometry store is updated.

OPERATION

The tool is programmed to a position adjacent to the Z face of the cube stylus. Use only the geometry offset and not the wear offset.

A setting move takes place which will calculate the error of the tool tip position.

eg. G65 H1 P#100 Q21
G65 H1 P#124 Q50600
G65 H1 P#120 Q9
M98 P9016

ERROR

591 Format Error

A value was not found in #124
(Default Occured)

592 Probe Open

The stylus is in contact with the workpiece before the reference move occurs.

The stylus is deflected by contamination in the probe eyelid (remove and clean) or by probe malfunction (check probe by diagnostics).

593 Probe Fail


The target face was not found within 4 mm of its expected position.

Check target value.

Check probe position prior to the macro cycle starts.

FUNCTION

TO SET A TOOL IN THE Z DIRECTION. TO ZERO THE WEAR OFFSET
AND ESTABLISH A NEW GEOMETRY OFFSET.



MACRO :9019

<u>INPUT DATA</u>	Variable Name
Inch/metric	#100
Traget Face Position	#126
Tool No	#120

OUTPUT DATA

The tool wear store is zeroed and the geometry store is updated.

OPERATION

The tool is programmed to a position adjacent to the Z face of the cube stylus. Use only the geometry offset and not the wear offset.

A setting move takes place which will calculate the error of the tool tip position.

eg. G65 H1 P#100 Q21
G65 H1 P#126 Q50600
G65 H1 P#120 Q9
M98 P9016

ERROR

591 Format Error

A value was not found in #126
(Default Occured)

592 Probe Open

The stylus is in contact with the workpiece before the reference move occurs.

The stylus is deflected by contamination in the probe eyelid (remove and clean) or by probe malfunction (check probe by diagnostics).

593 Probe Fail


The target face was not found within 4 mm of its expected position.

Check target value.

Check probe position prior to the macro cycle starts.

RENISHAW METROLOGY LTD

FIG 1



SEE EXAMPLES 1 and 2

Example 1

```
% (datum 4 faces of the cube)
G28 UO W0
T0303
* GO X80. Z-247.
G65 H1 P#100 Q21
M98 P9020
G98
G65 H1 P#126 Q-257000
M98 P9010                                Face 1
* GO X24.
* Z-275.
G65 H1 P#124 Q44000
M98 P9011                                Face 2
* GO Z-303.
* X80.
G65 H1 P#126 Q-293000
M98 P9010                                Face 3
* GO X136.
* Z-275.
G65 H1 P#124 Q116000
M98 P9011                                Face 4
* GO Z-247
* X80
G28 UO W0
T0000
M30
%
```

* Alternatively protected positioning can be used.
See macro :9014.

Cont/d.

Example 2

```
% (set a Turning Tool Face)
G28 U0 W0
T0404
* G0 X80. Z-250.
G65 H1 P#100 Q21
M98 P9020
G98
G65 H1 P#126 Q-260000
G65 H1 P#120 Q4
M98 P9019                                     Face 1
* G0 X130.
*      Z-275.
G65 H1 P#124 Q110000
G65 H1 P#120 Q4
M98 P9016                                     Face 4
G28 U0 W0
T0000
M30
%
```

* Alternatively protected positioning can be used.
See macro :9014.

APPENDIX

TYPE 1 TOOL SETTING INSTALLATION REQUIREMENTS

KIT NO. A/4012/0475

TAPE NO. A/4012/0476

This package is intended for installation where no user input/outputs are provided, and particularly for the installation of the 'TS20' probe which outputs a level signal for skip.

REQUIREMENTS

1. This software is to be installed on the Fanuc OTA Control.
2. User Macro A.
3. G31 skip option.
4. No user inputs/outputs required.
5. Memory Capacity 7 metres approx.
6. Basic Move Control Factor

Must set variable #510 to optimise the basic move cycle. Typical value is between 250 and 500. It is a multiplication factor which modifies the distance that the probe retracts off the surface before the final gauging move takes place. The software uses a maximum retract factor of 500 as a default value if #510 is zero.

INSTALLATION DETAILS

Refer to the TS20 Data Sheet H/2000/2110 for connection details.

In the case of an FI5 inductive interface see connection diagram as shown.



SOFTWARE

1. All inputs etc. as described in user guide H/2000/6016 are applicable, except for the following:-
 - a. Protected positioning :9014. It is not necessary to use input G65 H1 P#1115Q1. There is no false trigger alarm 587.
 - b. Datum the tool probe :9010 and :9011. It is not necessary to use input G65 H1 P#1118 Q1 for probe to probe calibration.
 - c. User outputs U014 and U015 will not be addressed in the software.
2. Examine the Program Directory and ensure that the following program numbers are available for use:

09025
09026
09010
09011
09014
09016
09019
09020
09021

Note. When this package is installed with the inspection software tape A/4012/0463, the protected positioning macro 09014 provided with this software must be used.

CONNECTION DIAGRAM



Note:

The internal SSR relay across pins TB1-16 and TB1-14 is reversible in its socket to select either N.O. or N.C.