

QuickCAM 2D Design

Printed Circuit Board Tutorial

Covers:

- Defining Billet
- Using shape boolean tool to combine shapes
- Importing Gerber files
- Grouping shapes together
- Creating an offset path
- Creating Offset Outside and Drill machining plans

This tutorial show how QuickCAM 2D Design can be used to manufacture a printed circuit board from a Gerber (RS247X) file.

Although there are no particular PCB designing tools, the software can be used to make minor modifications to an existing Gerber design.

Define working area (billet)


Define the size of the billet needed to create the PCB - for this example, the Gerber used is about 40mm square, so set the billet slightly bigger at 50 by 50.



This can be done as the software starts, or by clicking the resize material icon:

Create the PCB shape for cutting out

If the PCB needs to be fitted into a housing, there are various tools to help create the correct shape. For this example we know that the PCB must fit within a 45mm tube.



Select rectangle tool from the toolbar, or press **R** on the keyboard

To draw the rectangle at an exact position, use the co-ordinate entry boxes at the top of the design screen.



Absolute coordinate


Make sure the Absolute / Relative button is showing the absolute mode icon. Enter X5 Y5 into the co-ordinates and press OK

The system now wants to know the opposite corner of the rectangle, again use the coordinate entry boxes to specify a relative position to the last one entered.



Here, enter a relative size of X40 Y40. Pressing OK will now create a rectangle with 5,5 as the bottom left corner and 45,45 as the top right

Now create the 45mm diameter circle which we can use to clip the rectangle:




Select the circle tool from the toolbar, or press **C** on the keyboard

Enter X25 Y25 into the absolute coordinate edit boxes and press OK to define the centre of the circle

Change to relative mode and enter X22.5 Y0 and press OK to define the circles radius as 22.5 (45mm diameter)

Now select both the rectangle and the circle,





Move the mouse pointer to the left, bottom corner of the items we wish to duplicate

Press and hold the left mouse button

Now drag, whilst holding left mouse button down, the mouse to the top right corner of the design (as shown above) and let go of the mouse button

Alternatively, hold down SHIFT and click on each shape in turn

Now both items are selected, the Combine Shape tool will be active
NB, you must have more than one shape selected to use this tool



Choose the Intersection operation and you will see the result on the drawing screen in thick blue lines

Experiment with the other options to see how else this powerful tool can be used

The shape combine tool only works on closed shapes that have an area


- single lines will not be included in any boolean operations

- shapes such as open arcs will be automatically closed

Import the Gerber PCB design


For this tutorial, we are going to use a Gerber file which is installed with QuickCAM 2D Design into \My Documents\Denford\Gerber Files

The file is called **LightSwtch.gb0**



From the File menu, select Import
From the file import dialog, choose **Gerber PCB (*.gb*)** as the file type
Then browse your PC to find the LightSwitch file


When the PCB appears in the drawing, it is a good idea to group the tracks together to make life easier later on



With all the tracks selected, right click and then select the Make Group option from the menu

When you now click on any of the circuit tracks, the whole design will be selected

The one grip in the lower left corner of the group will allow the tracks to be positioned as one



Create cutter path

There are two ways in which a cutter path can be created to machine isolation gaps around the tracks

The first is to create an offset path from the design screen - that way a follow path can be used in the CAM wizard and the exact diameter of the engraving tool need not be known

The other is to simply define a suitably small cutter (eg, 0.5mm diameter) and use it to create an offset toolpath within the CAM wizard

To create an offset path in the design, select the tracks group and choose the **Create Offset Path** tool from the toolbar  or the Draw menu



If your cutter produced roughly 0.5mm wide cuts, then create and offset path of 0.25mm on the outside of the shapes



Look out for tracks that are too close together - the offset path will not be created where it would mean cutting into another track

Alternatively, just run the CAM wizard to create a CNC program

For this example we have setup a 0.5mm engraving tool and material settings (feed / speed) for soft wood which should be fine for single layer copper -clad board and an 1/8" (3.175mm) slot mill for cutting out the PCB.


Setting up tools and materials is covered in another tutorial.



Click the toolbar button:  or select **CAM Wizard** from the Generate menu

Choose the correct material as this will affect the speed, feed and tool step-down depth in the final CNC program

Click Next >



Choose the machining plan **Outside Offset**

Make sure you select the correct tool as this effects the distance of the tracks' offset

Set a cut depth of about 0.25mm

Select the tracks by clicking each one in turn, or drag the selection box across all tracks

Now press OK

We now want to have the CNC spot-drill the pad centres (if you had a small drill defined, it would also be possible to drill all the way through)

Select the machining plan **Drill**

Keep the engraving tool selected

Keep cut depth to 0.25

Click Select All in order to choose all the points for spot-drilling

The points are created when the Gerber file is imported. The system generates points at the centre of every Gerber FLASH pad operation. It is possible that too many or too few points are created depending upon the file


Next, select another **Outside Offset** plan

Select the 3.175mm slot mill


Set a cut depth of 1.8mm (just enough to break through the board)

Click on the PCB shape and press OK

Click Next > simulate and post out the CNC program



The simulation in progress



The finished PCB

Try and add the single line text yourself (see the Key Fob tutorial for more details on how to do this)