




MICROMILL 2000

Please note that this machine has **never** been set up and used. Other than the faulty circuit board it looks in brand new condition.



This is where the visible damage to the circuit board is. You just see that the plastic housing of the IC is damaged and this is also where the strongest smell of burning could be detected.

This fuse has blown and was replaced once with the spare provided.