







IF IN DOUBT ASK



2 CORE SCREEN
EARTH AT
DRIVE END




SUPPRESSOR
(RS 210-364)



0.2mm WIRES
SOLDER TO
SPINDLE DRIVE

SPRINT 400
SPINDLE DRIVE



IF IN DOUBT ASK

< 42 WAY HARTING CONNECTOR
SEE SHEET 3

DENFORD MACHINE TOOLS LTD

BRIGHOUSE

WEST YORKSHIRE

DRN BY A McHENRY

DATE 20-2-94

A3- 100252

STARTURN
SPINDLE DRIVE
[STARTURN]
[GR7]

SHEET 7