



This is when the laser cartridge is “leaking” The gold coated plastic material Mylar you are using is the material this issue is most visible. If you run the application on i.e. wood you will most likely not see this. However, there is unfortunately nothing you can do. A laser exchange is what one need to do if this is essential for the application.



# Graphic



The “leaking” or “shadow” appears here, where the carriage change direction.