










ST	F	R	-24v	P-P	REF	COM	FRQ	LOW	FLA	FLB	FLC
59	59	58		57	56	55				73	37

R41	R38	T1	EC1	EC2	ST1	U	V	W	L1	L2	L3
3		1	71	72		10	11	12	7	8	9

COMBIVERT
CONNECTIONS

74	73	72	71	65	37	28	26	24	23	22	21	19	17	16	14	14	12	11	10	9	8	7	6	5	4	3	2	1	N
----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	---	---	---	---	---	---	---	---	---	---



USED ON MACHINES
WITH AUTO LUBE SYSTEM

EASIMILL (COMBIVERT 3PH+N)
WIRING DIAGRAM MAGNETIC
PANEL

SHEET No.
OF
CONT. ON
SHEET No.