


















QUADRANT GEAR	TOP LEVER	3M/M L'SCREW PITCHES AND FEEDS IN M/M												GEAR LEVER
		G	D	G	C	E	G	D	F	C	D	B	A	
		2	1	4	1	2	5	2	3	2	3	2	2	
IN	LEFT	7	6		5,5		5		4,5		4			
		2,140	1,830	1,710	1,680	1,590	1,530	1,470	1,375	1,340	1,220	1,100	0,980	
		0,840	0,720	0,670	0,660	0,620	0,600	0,580	0,540	0,530	0,480	0,430	0,380	
	CENTER	3,5	3				2,5				2			
		1,070	0,920	0,850	0,840	0,790	0,760	0,730	0,680	0,670	0,610	0,550	0,490	
		0,420	0,360	0,340	0,330	0,310	0,300	0,290	0,270	0,260	0,240	0,220	0,190	
	RIGHT	1,75	1,5	1,4		1,3	1,25	1,2		1,1	1	0,9	0,8	
		0,540	0,470	0,430	0,420	0,400	0,380	0,360	0,340	0,330	0,300	0,280	0,240	
		0,210	0,180	0,170	0,160	0,156	0,150	0,144	0,135	0,132	0,120	0,108	0,096	
OUT	LEFT		0,75	0,7				0,6			0,5	0,45	0,4	
		0,260	0,230	0,220	0,210	0,200	0,190	0,180	0,170	0,160	0,150	0,140	0,120	
		0,105	0,090	0,084	0,082	0,078	0,075	0,072	0,068	0,066	0,060	0,054	0,048	
	CENTER		0,375	0,35		0,325		0,3		0,275	0,250	0,225	0,2	
		0,134	0,114	0,107	0,105	0,990	0,950	0,910	0,850	0,840	0,760	0,690	0,610	
		0,052	0,045	0,042	0,041	0,039	0,038	0,036	0,034	0,033	0,030	0,027	0,024	
	RIGHT			0,175				0,15			0,125		0,1	
		0,067	0,057	0,054	0,052	0,049	0,048	0,045	0,042	0,040	0,038	0,034	0,030	
		0,026	0,022	0,021	0,020	0,019	0,019	0,018	0,017	0,016	0,015	0,014	0,012	