





F1 MAIN POWER
F2 TRANSFORMER
F3 FAN
F4 SPINDLE DRIVE
F5 24V FROM TRANSFORMER

10A
3.15A
3.15A
6.3A
6.3A



MICROMILL 2000
RELAY AND FUSE
WIRING

SHEET 2
MICROMILL
DENSTEP