


CIRCUIT BY 'GREENBAT'

ALTERATIONS



DANFOSS 3~ CONTACTOR


T.D.S. 1/1.1/2.1.3 & 5. 'VICEROY' METAL LATHE.
3 PHASE WIRING DIAGRAM.

DENFORD MACHINE TOOLS LTD.		DRAWN <i>[Signature]</i>		MAT.	
(Inc.) DENFORD SMALL TOOLS (BRIG) LTD.		CHECKED		MAT. SIZE	
BRIGHOUSE,		PASSED		No. REQD.	
YORKSHIRE.		DATE 7.10.71		DRAWING No.	
				Sk.360/7.	

LIMITS ON DIMENSIONS UNLESS OTHERWISE STATED.

ANGULAR $\pm \frac{1}{2}^{\circ}$ 3 PLACE DECIMAL $\pm .005''$

FRACTIONAL $\pm .010''$ 4 PLACE DECIMAL $\pm .0005''$



DANFOSS ~ CONTACTOR

FRACTIONAL $\pm .010''$ 4 PLACE DECIMAL $\pm .0005''$

G.A.FL0119/65